

TCC Landsite ELECTRICAL Repair 'ESTIMATE'

January 2018

REPLACE electrical panel located in kitchen with larger 'service' panel.

Includes NEW circuit- 'breaker'-panel and NEW breakers.

Removal of 'small' panel located above existing panel

AND consolidating into ONE panel.

REPAIR / REPLACE electrical panel located on 'corner' of POLE BARN.

Using panel 'removed' from kitchen - and re-wiring panel as necessary.

REPLACE of electrical panel located behind 'stage' in POLE BARN.

Includes NEW larger panel – NEW circuit-breakers

AND re-wiring panel as necessary.

'ESTIMATE' for completing ALL these repairs - \$ 2100.